

Bryan W. Shaw, Ph.D., P.E., *Chairman*
Toby Baker, *Commissioner*
Richard A. Hyde, P.E., *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

June 30, 2015

Mr. Joshua Mair
Public Works Supervisor
City of Helotes
PO Box 507
12951 Bandera Road
Helotes, Texas 78023

Re: Municipal Separate Storm Sewer System (MS4) Phase II Comprehensive Compliance Investigation (CCI) at: City of Helotes (Bexar County), Texas
RN105484679, TCEQ ID No.: TXR040560, Investigation No.: 1252432

Dear Mr. Mair:

On May 06, 2015, Mr. Jack Higginbotham of the Texas Commission on Environmental Quality (TCEQ) San Antonio Region Office conducted an investigation of the above-referenced facility to evaluate compliance with applicable requirements for stormwater. No violations are being alleged as a result of the investigation; however, please see the additional issue in the summary of investigation findings attached to this letter.

The TCEQ appreciates your assistance in this matter and your compliance efforts to ensure protection of the State's environment. If you or members of your staff have any questions regarding these matters, please feel free to contact Mr. Jack Higginbotham in the San Antonio Region Office at 210-403-4090.

Sincerely,

A handwritten signature in blue ink, appearing to read "Joy Thurston-Cook".

Joy Thurston-Cook
Water Section Team Leader
San Antonio Region Office

JTC/JAH/adj

Enclosure: Summary of Investigation Findings

Summary of Investigation Findings

CITY OF HELOTES MS4

Investigation #

1252432

Investigation Date: 05/06/2015

, BEXAR COUNTY,

Additional ID(s): TXR040560

No Violations Associated to this Investigation

ADDITIONAL ISSUES

Description	Additional Comments
Item 1	Ensure illicit discharge detection and elimination investigations/inspections are documented.